


Case study success story

Image shift correction to facilitate printer replacement

The problem

- A law firm wished to replace existing printers with that of another manufacturer. One host system application was hard coded to print an image at the bottom left hand corner of the page. Due to differences between the operation of the paper feed guides on the proposed replacement printer and the existing devices the hard coded image to fell off the page in initial testes with the replacement printer.




Case study success story

Image shift correction to facilitate printer replacement

The solution

- docQrules was installed and configured using its Advanced Mode to apply a special custom script which identifies print jobs with this hard coded image and modifies the job to reposition the image so that it prints out in the correct position with the replacement printer.



Benefits

- The end user was able to select the desired alternative printer and avoid the expense of recoding the host system application.